




KLONDIKE SLEDGE PLAN

Your sledge should be at least 6 feet long and 18 inches wide. This drawing is an authentic design, but your own design is good, too. Use your imagination. Paint your sledge bright colors. Varnish the bottoms of the runners, then wax them before use. Add accessories. A tarp will keep your equipment dry. Use screws in place of nails. Drill first to avoid splitting.



Bill of Materials

- 2 pcs. 4"x1/2"x6'6" - Runners
- 6 pcs. 1"x1"x18" - Cross
- 4 pcs. 4"x1/2"x5' - Floor Boards
- 8 pcs. 1"x2"x6" - Upright Supports
- 2 pcs. 1"x2"x40" - Rear Uprights
- 2 pcs. 1"x2"x32" - Second Rear Uprights
- 2 pcs. 1"x2"x25" - Second Front Uprights
- 2 pcs. 1"x2"x18" - Front Uprights
- 1 pc. 1"x2"x18" - Front Runner Cross Piece
- 2 pcs. 1/2"x2"x6' - Hand Rails
- 1 pc. 2"x2"x18" - Tow Bar
- 4 pcs. 1"x2"x18" - Back Cross Slats